



Figure 3-8: Naturally reclaimed riffle habitat on July 31, 2001, at the site of the historical 1996 avulsion into Ridgefield Pit 1 on the East Fork Lewis River. The pool, which remains, is to the right of the photo behind the new channel bank.



Figure 3-9: Panoramic view of Ridgefield Pit 1 on July 31, 2001, which has reverted to off-channel habitat after five years of natural deposition. The main channel of the East Fork Lewis River is behind the viewer and is connected via a backwater slough-like channel.